


Blueprint Stand with Brackets

Assembly Instructions

for MODEL 613



PARTS LIST

Item	Descrip	QTY.	
А		Horizontal Frame	1
В		Side Frames	2
С		Cross Bar	1
D		Vertical Frame	1
E		Hanger	12
F		Spring	12
G		Setting Knob	4
Н		Screw	2
I	0	Washer	2
J		Locking Caster	2
К		Caster without Lock	2
L		Tube Plug	2
М		Wrench	1


Tools required for assembly: Phillips screwdriver

Page 1 of 2 www.adircorp.com

Blueprint Stand with Brackets

Assembly Instructions

for MODEL 613



4. Insert Tube Plugs (Part L) into top of vertical frame. **5.** Adjust the Horizontal frame (Part A) to paper size and tighten the setting Knobs. Insert the Locking Casters (part J) to front of Horizontal frame. Insert casters without Lock (part K) to rear of side frames. 6. Place spring (Part F) onto top of hanger (part E) small end down (x12). Guide hanger into holes of vertical frame, placing the spring side into top holes first, and then push up hanger placing the bottom of hanger into bottom holes.